



River restorations in River Keravanjoki, Hyvinkää, Finland



15.10.2003
Before



Area for the fishpass

After



Harri Aulaskari
Planner
Environmental Management and Water Use division
Uusimaa Regional Environment Centre
harri.aulaskari@environment.fi
<http://www.environment.fi>

© Juha Kuvaja

15.10.2003
Before



Area for the fishpass


After



© Juha Kuvaja

Harri Aulaskari
Planner
Environmental Management and Water Use division
Uusimaa Regional Environment Centre
harri.aulaskari@environment.fi
<http://www.environment.fi>

Filter fabric: double layer on the bottom



© Juha Kuvaja

Filter fabric: The third layer over the stones



© Juha Kuvaja



© Juha Kuvaja



© Juha Kuvaja

Harri Aulaskari
Planner
Environmental Management and Water Use division
Uusimaa Regional Environment Centre
harri.aulaskari@environment.fi
<http://www.environment.fi>

Filter fabric have been cutted away manually,



Harri Aulaskari
Planner
Environmental Management and Water Use division
Uusimaa Regional Environment Centre
harri.aulaskari@environment.fi
<http://www.environment.fi>

Spring 2006



© Juha Kuvaja



© Juha Kuvaja



© Juha Kuvaja



© Juha Kuvaja

Spring 2006



© Juha Kuvaja



© Juha Kuvaja

Summer 2006





© Juha Kuvaja



© Juha Kuvaja

Restoration in brook Longinoja, Helsinki, Finland



20.3.2006



© Juha Salonen

24.3.2006



© Juha Salonen



Autumn 2005



Summer 2006

© Juha Salonen